

Figure 1



Figure 2



Figure 3a



FIG. 3b



Figure 4

Figure 5





Figure 6



Figure 7



Figure 8



Figure 9

Figure 10




46
OUTER WALL FLANGE
CAPTURED BY
38
LOCKING SLOT
BOTTOM
OF EXTERNAL RIB
54

FIG. 12


B
A
38
52
PREVENTS
FURTHER
ROTATION
50
RIB RIDES
OVER THIS
BUMP
48
BUMP PREVENTS
ROTATION
TOWARDS
RIGHT
14

FIG. 11



FIG. 13



FIG. 14



FIG. 15



FIG. 16



FIG. 17